



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor JK

Minerals Regulatory Program

Date of Report: 04/08/2008

Mine Name: Roundabush 1

Operator Name: Worthen / Williams LLC

Permit number: M0450027

Inspection Date: 04/03/08

Time: 9:30 am

Inspector(s): Leslie Heppler

Other Participants: none

Mine Status: Active

Weather: Sunny and cold

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: This was a routine inspection

Inspection Summary: Mine overall was in good shape. No deleterious material was found. Roads were in good condition, but mine was not active at the time of the site visit and it is not known if a water truck was used during hauling for dust control. A small loader was on site. Numerous stockpiles have been processed, but still on site. Topsoil stockpile had vegetation growth. Note photos are attached.

Conclusions and Recommendations: Operator should review the Mine site for public safety issues and highwall safety. Future inspection visit is to include detailed GPS survey.

Inspector's Signature

Leslie Heppler

Date:

04-08-08

080001

Photos taken 04-03-08



lah:pb

cc: Robert Worthern
Agency (Fee)
GPS map and Photos